
SURVEYOR LOCATION REPORT

I hereby certify to the parties named above that the real estate described herein was inspected under my supervision on the date indicated and that to the best of my knowledge, this report conforms with the requirements contained in Sections 27 through 29 of 865 IAC 1-1-12 for a SURVEYOR LOCATION REPORT. Unless otherwise noted there is no visible evidence of possession lines found.




Note: Obtaining accurate and complete data on or near the perimeter of larger tracts is beyond the scope of the report. The location of any improvements and fences shown have been estimated. Due to the size of the tract and inadequate reference monumentation, the accuracy of this report is limited to ±10 feet. A staked boundary retracement survey is recommended if precise locations are desired.

Note: Interior fences not shown on this report.

is affected by any legal drain(s) or pipeline(s).

Davis Road



(18' Pavement) (Existing Roadway) 208.20 8 -Trees & Bushes± See Detail (L.A.±) Asphalt-Drive± 300.0' 113.6' 498. 365.4 69.3 Driv Area± 208' Tract II Barn & Stables 299.80 207.60 Point of Beginning-Point of Beginning Tract II Tract I



HAHN SURVEYING GROUP, INC.

Land Surveyors 8925 N. Meridian Street, Suite 120 Indianapolis, IN 46260

PHONE: (317) 846-0840 / (317) 846-4119 FAX: (317) 846-4298 / (317) 582-0662 EMAIL: orders@hahnsurveying.com

www.hahnsurveying.com



CERTIFIED: 08/03/2021

Chad L. Brown Registered Land Surveyor, Indiana #21100002

Drawn By: MAG Job No.: S21-4803 Sheet 2 of 3